



TincQ!
Material Solutions



Tempcoat®

A Corrosion Under Insulation (CUI) Solution

CUI is a severe problem for industrial equipment, and has led to many corrosion failures over the years. CUI appears when under insulated equipment salts out of the environment accumulate and combined with condense it results in an aggressive environment. Due to the coverage of the insulation detection of CUI is problematic and mostly appears in a far degraded state.

With Tempcoat the insulation will be replaced by a insulating coating. Due to the adhesion accumulation of salts and condensation underneath the insulation is avoided. In this way the the mechanism of CUI is completely vanished. On top of this a temp-coated lining or storage tank can still be inspected and if corrosion still appears it can easily and in an early stage be detected.

TincQ bv

Joh. Mooijstraat 49
nl-8391 LP Noordwolde-Zuid (frl)

T: +31 561 430 502
M: +31 611 004 997

info@tincq.eu
www.tincq.eu